EVAC SERVICES LTD . Fire Warden Training

. Trial Evacuations

## TRIAL EVACUATION REPORT

Building Name RAUKURA Building				
Building Address 7 St Vincent Avenue, Remuera.				
Name of Person conducting Trial : Paul Walters Phone N			Phone No:	027 290 4688
CPU Advised	Yes / <del>No</del>	NZ Fire Service Comm	s. Centre advised	Yes / <del>No</del>
Date Trial Conducted: 18 June 2020 Time of Trial: 15.00 hours				s
1. Time taken to complete evacuation of building 3 r				8 min 30 secs
2. Did Floor Wardens report promptly to the Building Warden?				YES
3. Was everyone evacuated?				NO
4. Could alarm be heard? (ask Wardens)				YES
5. Were wardens and staff members familiar with the Evacuation Procedures?				YES
6. Did wardens we	6. Did wardens wear identification?			
7. Was a call made to the Fire Service using 111?				MIMIC
8. Was the correct Assembly Area used?				YES
9. Was there a Building Assistance Register available?				YES
10. Are there evacuation procedure notices in place?				YES
11. Are exitways clear and can exit doors be opened without the use of a key (those checked				ed) YES
12. Has firefighting	12. Has firefighting equipment been serviced in the last 12 months? (those checked)			
13. Have Wardens	13. Have Wardens been trained?			
14. Was anyone inj	jured?			NO
15. Next Training is	s scheduled for: Decem	nber 2020.		
Comments : Good evacuation practice.				
111 call mimicked as per Fire Service instructions.				
Due to inclement weather, residents not asked to fully evacuate.				
Full evacuation of building, staff allocated to knock on doors and assist residents to evacuate				
Entrance gate staffed to prevent vehicle entry. Alarm panel checked.				

Signed by : Paul Walters